STRUCTURAL SOUNDNESS CERTIFICATE

This is to certify that I visited the BLOOMINGDALE SCHOOL,

D No:10-234, PORANKI, YSR TADIGADAPA MUNICIPALITY, KRISHNA DISTRICT. The

School has RCC Roofed G+2 structures with walls of brick work and sufficiently

ventilated and lighted. Sanitary facility arranged separately for boys and girls. The

teachers and students can move one room to another comfortably. The total

school building is structurally sound.

Station:Vijayawada

Date :18.11.2022

ASST. ENGINEER (MAINTENCE)

Olo. the Engineer-in-chief

Panchayathi Raj Department, Vijayawada.